

# PERFORMA FOR THE SAFETY OF SCHOOL BUILDING

## PART I

(To be filled by the Head of the School/Institute)

1. Name the School : Universal Public Sr. Sec. School
2. Location : Talwandi Sabo
3. Plot Area : 88481.25 SQ FT
4. Plinth Area : ~~46681~~  
12327.75 SQ FT 731579 Sq. Ft
5. Number of Stories : Three Storays
6. Year construction of Building
7. If the Building has been Constructed under the supervision of the qualified Engineer, the following details may be given
- (a) Name of Engineer with qualification : -
- (b) Address : -
- (c) Set of structure drawing used on the construction if available : -
- (d) Name and address of Architect with qualification : -
8. Whether building has been constructed
- (a) For the purpose of school :  Yes/No
- (b) Or converted for use as school :  Yes/No
9. Material used for roof
- (a) R.C.C. Slabs/RBRC :  R.C.C./R.C.C. Slabs
- (b) R.S. Joints and Batons :  Yes/No
- (c) Wooden joints :  Yes/No
- (d) Tile Terracing :  Yes/No
10. Material used for walls
- (a) Mud mortar :  Yes/No
- (b) Cement mortar :  Yes/No
- (c) Plaster : 1. Lime Mortar :  Yes/No
2. Cement Mortar :  Yes/No
11. Flooring
- a) Conglomerate :  Yes/No
- b) Terrazzo :  Yes/No
- c) Brick Paving/Flooring :  Yes/No
12. A detailed drawing indicated of dimension of the rooms along with the size & location of doors & windows :  Yes/No

President  
Management Committee  
Universal Public School  
Talwandi Sabo - 15102 (B.T)

b. Whether all classrooms are provided two door system.

Yes

c. Whether fire safety measures have been Yes adopted and are in working condition

Yes

*Sd/-*

Dated 10-05-2023

Signature of principal with school stamp

Universal Public Sen. Sec. School  
Talwandi Sabo  
Bathinda (PB.)  
Affiliation No. 1631098

(FOR THE USE OF THE PWD B&R DEPARTMENT)

a) I Balwinder Singh S.D.E along with Cumwinder Singh have visited this school on 15/05/23 and have inspected it from all angles of safety and found it fit for normal use as school building.

b) In case any addition, alteration, extension or modification of this building is to be carried out, it should be carried out under the supervision of technical qualified Engineer, and after its completion, this certificate may again be obtained from the undersigned.

c) in case the building is affected by flood or if there is settlement to walls foundations edging or roof, immediate inspection of the undersigned be arranged to check the stability and safety of the building

d) The building can be safely occupied for normal use up to 31/03/24

e) Inspection fee amounting to Rs 10,000/- has been deposited by the school vide G.R. NO. 1741982

dated :- 10/05/23

*[Signature]*

President  
Management Committee  
Universal Public School  
Talwandi Sabo-151302 (BTI)

*[Signature]*

Principal  
Universal Public Sen. Sec. School  
Talwandi Sabo  
Bathinda (PB.)  
Affiliation No. 1631098

*[Signature]*

Universal Public Sen. Sec. School  
Talwandi Sabo  
Bathinda (PB.)  
Affiliation No. 1631098