


**PROFORMA FOR THE SAFETY OF SCHOOL BUILDING
PART- 1**

(To be filled by the Head of School/ Institute)

1. Name of the School : Universal Pub. Sec. Sch.
2. Location : Talwandi Sabo
3. Plot Area : 88481.25 SQ FT
4. Plinth Area : 18327.75
5. Number of Storey's : Three Storeys
6. Year of Construction of Building :
7. **If the building has been constructed under the supervision Of the qualified Engineer, the following details may be given** : *Constructed under school management supervision*
 - a) Name of the Engineer with qualification : -
 - b) Address of Engineer : -
 - c) Set of Structural drawings used in the construction, if available : -
 - d) Name & address of Architect with qualification : -
8. **Whether the building has been constructed for the purpose** :
 - a) School : YES/ NO
 - b) Residential Purpose and converted for use as a School : YES/ NO
9. **Materials used for roofs**
 - a) R.C.C. Slabs/R.B.C. Slabs : YES/ NO
 - b) R.S. Joist & Battons : YES/ NO
 - c) Wooden joists & Battons : YES/ NO
10. **Materials used for walls**
 - a) Mud Mortar : YES/ NO
 - b) Cement Mortar : YES/ NO
 - c) Lime Mortar : YES/ NO
11. **Flooring**
 - a) Conglomerate : YES/ NO
 - b) Terrazo : YES/ NO
 - c) Brick Paving. : YES/ NO
12. **A detailed drawing indicating dimensions of the rooms Alongwith size and location of doors and windows (Attached)** : *yes*


 Principal
 Universal Public Sec. School
 Talwandi Sabo
 Bathinda (P.B.)
 Affiliation No. 1631098
 Signature with Stamp of the seal
 Of the School/Institution.

b. Whether all classrooms are

Yes

provided two door system.

c. Whether fire safety measures

Yes

have been Yes adopted and are in working

condition.

Dated

Principal
Universal Public Sen. Sec. School
Talwandi Sabo
Bathinda (PB.)
Affiliation No. 1631098

Signature of Principal with school stamp

(FOR THE USE OF THE PWD B&R DEPARTMENT)

- a) I Balwinder Singh S.D.E along with Gurwinder Singh (IE) have visited this school on _____ and have inspected it from all angles of safety and found it fit for normal use as school building .
- b) In case any addition ,alteration ,extension or modification of this building is to be carried out ,it should be carried out under the supervision of technical qualified Engineer, and after its completion , this certificate may again be obtained from the undersigned.
- c) In case the building is affected by flood or if there is settlement to walls foundations edging or roof ,immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- d) The building can be safely occupied for normal use up to 31 - March 2023
- e) Inspection fee amounting to Rs 10,000/- has been deposited by the school vide G.R. NO. 1741963

Dated:-

ਰੂਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਪ੍ਰਾਡਕ ਰੂਪ ਮੰਡਲ ਨੰ: 4.
ਭ ਡੇ ਮ ਸਾਖਾ, ਤਲਵੰਡੀ ਸਾਬੋ