


PROFORMA FOR THE SAFETY OF SCHOOL BUILDING
PART-1

(To be filled by the Head of School/ Institute)

1. Name of the School : Universal Public Sen. Sec. School
2. Location : Talwandi Sabo
3. Plot Area : 88481.25 Sqft.
4. Plinth Area : 31579 Sqft.
5. Number of Storey's : Three storeys
6. Year of Construction of Building : .
7. If the building has been constructed under the supervision Of the qualified Engineer, the following details may be given : Constructed under School management supervision
 - a) Name of the Engineer with qualification : -
 - b) Address of Engineer : -
 - c) Set of Structural drawings used in the construction, if available : -
 - d) Name & address of Architect with qualification : -
8. Whether the building has been constructed for the purpose :
 - a) School : YES/ NO
 - b) Residential Purpose and converted for use as a School : YES/ NO
9. Materials used for roofs
 - a) R.C.C. Slabs/R.B.C. Slabs : YES/ NO
 - b) R.S. Joist & Battons : YES/ NO
 - c) Wooden joists & Battons : YES/ NO
10. Materials used for walls
 - a) Mud Mortar : YES/ NO
 - b) Cement Mortar : YES/ NO
 - c) Lime Mortar : YES/ NO
11. Flooring
 - a) Conglomerate : YES/ NO
 - b) Terrazo : YES/ NO
 - c) Brick Paving : YES/ NO
12. A detailed drawing indicating dimensions of the rooms Alongwith size and location of doors and windows (Attached)



Principal
Universal Public Sen. Sec. School
Talwandi Sabo
Bathinda (PB.)
Affiliation No. 1631098


Principal
Universal Public Sen. Sec. School
Talwandi Sabo
Bathinda (PB.)
Affiliation No. 1631098
Signature with Stamp of the seal
Of the School/Institution.

(FOR THE USE OF THE PWD B&R DEPARTMENT)

- a) I Daljeet Singh S.D.E along with Rajinder Kumar have visited this school on 23/08/2024 and have inspected it from all angles of safety and found it fit for normal use as school building.
- b) In case any addition, alteration, extension or modification of this building is to be carried out, it should be carried out under the supervision of technical qualified Engineer, and after its completion, this certificate may again be obtained from the undersigned.
- c) In case the building is affected by flood or if there is settlement to walls foundations, edging or roof, immediate inspection of the undersigned be arranged to check the stability and safety of the building
- d) The building can be safely occupied for normal use up to 31 March 2025.
- e) Inspection fee amounting to Rs 10,000/- has been deposited by the school vide G.R. NO. 1744997 dated 09/08/2024.

Countersigned


Sub Divisional Engineer
Prov. Sub Div. PWD B&R No. 4
Talwandi Sabo